

333 Plingsten Road Northbrook, Illinois 60062–2096 United States Country Code (1) (847) 272–8800 FAX No. (847) 272–8129 http://www.ul.com

TUFV.SA12481 Equipment, Scaffolding

BAUMANN MOSTOSTAL SP ZO O UL STARZYNSKIEGO 1 08-110 SIEDLCE,POLAND

July 06, 2001

SA12481

Scaffolding equipment, Series MP800, MP1000 scaffolding, rated 25 lb/ft2; Models ROTAX, WALL, scaffolding, rated 50 lb/ft2. This equipment is Classified as to load carrying capacity only. The load carrying capacity of the individual component has been evaluated.

The separate parts of the scaffolding system are produced under the Classification and Follow - Up Service of Underwriters Laboratories Inc. Assembly of such parts in the erection of a scaffolding system is not inspected by Underwriters Laboratories Inc., but should be made in accordance with requirements of authorities having jurisdiction and the manufacturer's instructions.

LOOK FOR CLASSIFICATION MARK ON PRODUCT

A not-for-profit organization dedicated to public safety and committed to quality service